

Test report of vehicle trouble diagnosis

The Report is created by **THINKCAR**

Repair Shop

SN:988974701567

Test Time:10/04/2024 12:05

Vehicle Information

Model:HHR2LT

Year:2008

VIN:3GNCA53P78S722965

Vehicle Software Version:V10.22



Inspection Result

EOBD 7 problems exist

1.P0122 Throttle/Pedal Position Sensor/Switch A
Circuit Low

2.P0222 Throttle/Pedal Position Sensor/Switch B
Circuit Low

3.P0122 Throttle/Pedal Position Sensor/Switch A
Circuit Low

4.P0222 Throttle/Pedal Position Sensor/Switch B
Circuit Low

5.P2544 Torque Management Request Input Signal A

6.U0073 Control Module Communication Bus A Off

7.U0101 Lost Communication With TCM